

1527 E McLellan Rd. Mesa, AZ 85203 Direct: 480.703.5204 Kyle@NestHomeInspections.com

Confidential Inspection Report Prepared for: Shane Cook

> Inspection Address: 1248 N Regatta Dr Gilbert, AZ 85234

Inspection Date: September 14, 2016

*Inspected by:*Kyle J Hageman
AZ BOTR #42018



The contents of this report are for the sole use of the client named above and no other person or party may rely on this report for any reason or purpose whatsoever without the prior written consent of the inspector who authored the report. Any person or party who chooses to rely on this report for any reason or purpose whatsoever without the express written consent of the inspector does so at their own risk and by doing so without the prior written consent of the inspector waives any claim of error or deficiency in this report.

EXECUTIVE SUMMARY

NOTE: This analysis is not meant to be technically exhaustive but rather to highlight areas that repairs are needed or areas of long term future concern relating to maintenance and operation.

This **Executive Summary** consists of those items we feel need immediate attention or consideration. It is entirely the client's decision whether or not to include additional items from the **Building Component Checklist** they may feel are of concern and add them to our list of opinions as stated in the **Executive Summary**.

Note: Copies of permits (if they exist) with names and license numbers of all contractors who did work on this home is needed for warranty protection and to verify that concealed work was done properly. It is unknown if permits were obtained for any electrical, gas, mechanical and/or plumbing modifications and/or additions that may have been done to this home. The buyer should investigate during the inspection period.

1. EXTERIOR

- A. The low exterior masonry walls at landscaped areas surrounding the home do not appear to allow for proper drainage away from the home. There are signs of past ponding at these areas and improvement is needed.
- B. The yard watering system appears to be overwatering, especially at the planter boxes where moisture is held along the exterior stem wall, and needs correction.
- C. The basement window well needs vegetation and debris removed. There does not appear to be a drain at the window well area, care should be taken to avoid moisture penetration of this area. There does not appear to be a sump pump for this area.
- D. Although there is a floor drain at the bottom of the basement exterior steps, there does not appear to be a sump pump for this area. This drain needs to be further evaluated.
- E. The south yard gate is damaged and not operable, there is not pool barrier protection at the south yard area.
- F. The rear patio ceiling, beam and trim pieces are moisture stained below the above balcony area and should be further evaluated and corrected as needed.
- G. There is a hole through the kitchen west exterior wall that needs repair.
- H. The basement exterior step heights are uneven throughout the stair, with step heights higher than recommended and the difference in heights out of tolerance for safety. The stair handle rail does not terminate at the exterior walls and is also a potential hazard. The stairs need to be further evaluated and improved as needed.
- I. The basement bedroom enclosure does not appear to be original to the home, the bedroom does not have an exterior window and no means of ingress/ egress as needed.
- J. Consult a licensed contractor to further evaluate all conditions during the inspection period.

2. ROOFING

- A. Roof vents, jacks, and penetrations need mesh and recoating.
- B. The installation of a vent/ rain caps and spark arresters are needed at the chimney tops.
- C. Vegetation and debris needs to be removed from the roof surfaces.
- D. The wood shingles/ shakes are split/ damaged at numerous areas throughout but appear intact. The wood shingles/ shakes need to be monitored and repaired or replaced as needed.
- E. The installed roof to wall flashings appear to be channel flashings and not the proper step-flashings as needed with a shingle roof. This needs to be further evaluated and needs correction the next time the roofing is replaced.
- F. Roof valley flashing does not extend beyond the eave as needed and needs to be further evaluated and improved as needed.
- G. The roof eave gutters are clogged and need cleaning. The gutters show signs of past leakage at joints and need repair or replacement.
- H. Gutter downspouts are damaged/ disconnected or insufficient in length to direct water away from the exterior walls/ stem walls and need further evaluation and improvement.
- I. The rolled roofing installed at the roof chimney cricket does not appear fully bonded and needs further evaluation.
- J. The balcony floor appears bowed downward along the west edge/ termination and needs further evaluation and repair. There are signs of past leakage at the rear patio ceiling below this area, a licensed roofing contractor needs to further evaluate during the inspection period.
- K. Consult a licensed roofing contractor to further evaluate all conditions during the inspection period.

3. PLUMBING

- A. The gas line to the rear yard barbecue is heavily corroded/ damaged at grade and needs to be replaced. This is a potential hazard and needs immediate correction.
- B. The powder room toilet is not functional and the fill/ flush assembly appears to need repair or replacement.
- C. The hall bath toilet is not secure to the floor and needs to be reset.
- D. The laundry south hose bib does not appear to fully close as the attached waterline has a slow leak.
- E. We recommend (as an upgrade) replacing the interior and exterior water shut-off valves with ball valves for ease of operation and to prevent leaks.
- F. The master bath east and west sink drains are not properly connected and the sinks leak into the cabinets when the faucets are operated, corrections are needed.
- G. The master tub divert/ wand control does not have full range of motion due to the installed wall tile.
- H. The basement bathroom shower control spins 360 degrees with no stops which is a potential scald hazard and needs correction.
- I. Consult a licensed plumbing contractor to further evaluate all conditions during the inspection period.

4. ELECTRICAL

- A. The exterior outlets need to be GFCI protected for safety.
- B. The south yard west pilaster light is not secure and has exposed wiring. Several of these exterior pilaster lights are not functional and need further evaluation.
- C. There are several conditions at the main and sub panels that need further evaluation and correction including: There are abandoned wires located inside the main panel that need to be properly abandoned and removed, the main and panel breakers need to be completely and accurately labeled, the main panel has several open breaker spaces that need to be covered, the main panel has several weathered breakers that need further evaluation and may require replacement, electrical wire sheathing extends further into the panel than is recommended and the panel wiring appears crowded, and the main panel buss bar shows signs of past overheating/ damage, these items need to be further evaluated during the inspection period.
- D. Note: The installation of G.F.I. (ground fault interrupting) outlets at all "wet" areas such as the laundry room, garage, and the exterior.
- E. The master whirlpool tub pump motor is not bonded as required and needs correction.
- F. The breakfast nook and master bedroom exterior doors do not have installed exterior switched lights as needed for safety and need correction.
- G. The garage interior wall outlets are not GFCI protected as needed for safety.
- H. The laundry interior wall outlet is not GFCI protected as needed for safety.
- I. Attic electrical wire sheathing is missing near the attic electrical junction box penetrations and wiring is exposed and needs correction.
- J. The kitchen island has only a single outlet which appears insufficient for an island of this size. This GFCI outlet is tripped and will not reset, the outlet appears faulty and needs replacement.
- K. The cooktop downdraft vent is not operational. The outlet for this device tests without power and needs further evaluation.
- L. The kitchen west wall outlet south of the sink shows signs of past overheating and needs to be further evaluated and replaced as needed.
- M. Interior closet wall and ceiling open light fixtures are potential hazards as installed incandescent bulbs would not have appropriate clearance from combustibles or storage items. The fixtures need to be further evaluated and upgraded for safety.
- N. The basement bathroom wall GFCI outlet is tripped and does not reset. The outlet appears faulty and needs replacement.
- O. Consult a licensed electrical contractor to further evaluate all conditions during the inspection period.

5. HEATING AND COOLING

A. The west exterior wall HVAC condensate line does not extend beyond the wall and may cause moisture damage and needs correction.

- B. The underground air returns are dirty and need cleaning.
- C. The installed air filters at the ceiling air handler are dirty/ clogged and need replacement.
- D. Consult a licensed HVAC contractor to further evaluate all conditions during the inspection period.

6. INTERIORS

- A. We recommend the installation of smoke detectors in each bedroom. Carbon monoxide detectors need to be installed due to gas fixtures or appliances.
- B. The upper level and basement interior step heights are uneven throughout the stairs, with step heights higher than recommended and the difference in heights out of tolerance for safety. The basement stair handle rails do not terminate at the exterior walls and is also a potential hazard. The upper level stair railing and balcony railing spindle spaces are greater than current safety requirements. The stairs need to be further evaluated and improved as needed.
- C. The basement floor tile grout lines are moisture stained at the northeast end near the exterior door, the source of the moisture is undetermined and needs further evaluation.
- D. Consult a licensed contractor to further evaluate all conditions during the inspection period.

7. ATTIC, INSULATION AND VENTILATION

- A. The garage attic access pull-down plywood stair is not compliant with fire separation standards and needs replacement. Contact a licensed contractor for proper repair.
- B. The attic does not appear to be adequately ventilated; further evaluation and correction is needed.
- C. The kitchen pantry closet attic access cover is missing and needs replacement. A piece of R-30 fiberglass batt insulation needs to be attached to the attic access cover.
- D. Attic insulation levels appear to be below the current standard; we recommend adding insulation to achieve the current R-30 minimum standard.
- E. Attic batt insulation is displaced or missing at several random areas of the visible attic space and needs correction.
- F. Attic flex ducts from bathroom exhaust fans do not fully extend to the roof vent openings and should be improved as needed.
- G. Consult a licensed contractor to further evaluate all conditions during the inspection period.

8. KITCHEN AND BUILT-IN APPLIANCES

- A. The dishwasher and disposal could not be tested due to the leak at the kitchen sink drain pipe disposal area.
- B. The cooktop center burner control appears damaged, is not functional and the burner could not be operated. The Viking cooktop needs repair or replacement.
- C. The cooktop downdraft vent could not be made operational and needs correction.
- D. The disposal is leaking at the drain pipe connection and needs correction.

E. Consult a licensed contractor or repair specialist to further evaluate all conditions during the inspection period.

9. POOL, SPA AND EQUIPMENT

- A. Self- closing and self- latching devices need to be installed at doors to the pool area for pool barrier protection.
- B. Self- closing and self- latching devices need to be installed at gates to the pool area for pool barrier protection. Gates need to pull-out from and not push-into the pool area for barrier protection.
- C. The pet door may allow access to the pool area and needs correction.
- D. Entrapment prevention components need to be installed for pool safety.
- E. The pool drain cover is damaged/ missing and needs replacement.
- F. The pool equipment pump motor is not bonded as required and needs correction.
- G. There are gaps around the pool light switch where wiring is exposed, correction is needed.
- H. The pool plaster is discolored at shallow areas such as the steps and seats. The spa plaster surfaces appears worn/ rough and needs further evaluation, the spa surface is dirty and has surface debris and needs cleaning and further evaluation.
- I. The pool wall tiles are damaged or missing in at least two areas at the north and northeast ends where tile replacement is needed. The pool wall tiles need cleaning. The spa spillway has several hollow or not fully bonded tiles where repairs are needed.
- J. A portion of the flagstone pool nosing is loose and offset with missing mortar joins at the northwest end.
- K. Consult a licensed pool contractor to further evaluate all conditions during the inspection period.

NOTE: It is our recommendation that repairs be made by licensed contractors or experts familiar with proper methods of repair and for their ability to warranty. All items noted in this summary need to be investigated further during the inspection period. Any items in this summary that are to be repaired need to be corrected by contractors or experts qualified in each category.

BUILDING COMPONENT CHECKLIST SYSTEM: STRUCTURAL COMPONENTS

FOUNDATION	Foundation stem: ☐ Readily visible ☑ Not fully visible									
STEM	Type: ⊠ Slab	on grade ⊠ Concrete □ Masonry □ Pier □ Post tension								
	Condition: $oxtimes$ Appears satisfactory where visible $oxtimes$ See summary									
	Crawl area condition: ☑ N/A ☐ Satisfactory where visible ☐ See summary									
	Method used	to inspect crawl space: \square Fully accessed \square Not accessed								
	□Viewed thr	ough access Partially accessed due to owner contents								
	Weep screed:	□ N/A ☑ Typical ☑ See summary								
	caulked or sea	L) The joint between the exterior wall siding and the concrete stem wall should be aled at gaps for moisture and pest protection. (2) Small cracks or voids in the concrete ould be filled and the exposed areas should be repainted.								
FLOOR	Туре:	☑ Concrete ☑ Wood ☑ Not fully visible								
STRUCTURE	Condition:	\square Adverse conditions \boxtimes No visible adverse conditions \boxtimes See summary								
	Finished floor	level: ☑ Typically above grade ☑ See summary								
	to be further	L) Typical upper level wood floor and stair "pops and squeaks" are noticeable and need evaluated and corrected as needed. (2) The garage floor is cracked at random areas and nonitored and further evaluated as needed. (3) The basement is below grade and subject atrusion.								
WALL	Туре:	☑ Frame □ Masonry □ Concrete □ Other								
STRUCTURE	Condition:	☑ Appears satisfactory where visible ☑ See summary								
	Cracks:	☑ Typical ☐ Excessive ☐ See summary								
	Cladding:	☑ Stucco ☐ Masonry ☑ Brick veneer ☑ Hardboard siding								
	Condition:	☑ Appears satisfactory where visible ☑ See summary								
	Comments: (1) Gaps around framing, plumbing, mechanical, and electrical penetrations threexterior walls should be sealed for moisture and pest protection the next time the home is pair (2) Joints between dissimilar materials, such as stucco to wood, stucco to metal flashings, stuction window and door frames, etc., should be sealed and caulked the next time the home is painted. There are stress fractures in the stucco around windows and doors that result from movement are quite common. Random area small exterior wall stucco cracks should be repaired or sealed next time the home is painted. (5) The exterior wall masonry mortar joints need small random a repairs. (6) Some sections of the exterior frame and stucco walls do not have weep screed install terminations.									
ROOF AND	Type:	☑ Trusses ☑ Conventional ☑ Not fully visible								
CEILING STRUCTURE	Condition:	$oxtimes$ Adverse conditions \Box No visible adverse conditions \Box See summary								
J.M.OOTOME	Sheathing:	☑ Typical ☑ Not fully visible								
	Condition:	$oxtimes$ Appears satisfactory where visible \Box See summary								
	Comments:									

COLUMNS	House:	☑ Masonry ☐ Frame ☐ Wood ☐ Brick veneer ☐ N/A
	Condition:	$oxtimes$ Appear satisfactory where visible \oxtimes See summary
	Patio:	☑ Masonry □ Frame stucco □ Wood □ Metal □ N/A
	Condition:	$oxtimes$ Appear satisfactory where visible $\ootnotesize{\ootnotesize{\square}}$ See summary
	Comments:	

SYSTEM: EXTERIOR

EXTERIOR	Exterior doors:	☐ Generally operable ☐ Not operational							
DOORS	Condition:	☑ Appear satisfactory where visible ☑ See summary							
	Garage doors:	□ N/A ☑ Operable □ Not operational □ Manual ☒ Electric							
	Comments: (1) The east end. The doc	n obstructed \square Stops with resistance \boxtimes See summary ne overhead garage door lower panel is bowed outward and appears bent near the or is operational but needs to be further evaluated and reinforced as needed. (2) The door bottom weather stripping is damaged and needs replacement.							
EXTERIOR	Type: ⊠ Metal	□ Wood □ Vinyl ☒ Fixed □ Single pane ☒ Dual pane							
WINDOWS	Condition: ⊠ App	ear satisfactory where visible 🗵 See summary							
	A representative number of windows: ☐ Generally operable ☐ Not operational Comments: (1) Window screens may be missing, damaged or uninstalled at random locations. (2) The exterior windows were dirty and not fully visible, (windows may not be fully visible due to shade screens, window film, etc.) the windows should be cleaned and further evaluated at the buyer's								
TDINA	discretion.								
TRIM EAVES	Trim condition:	☐ Adverse conditions ☒ No visible adverse conditions ☐ See summary							
SOFFITS	Eave condition: ☐ Adverse conditions ☒ No visible adverse conditions ☐ See summary								
FASCIAS	Soffit condition: ☐ Adverse conditions ☒ No visible adverse conditions ☐ See summary								
	Fascia condition:	☐ Adverse conditions ☒ No visible adverse conditions ☐ See summary							
	Comments: (1) The exterior wood trim pieces, especially those surrounding exterior windows, are weathered and need service/ repairs and repainting. (2) Exterior wood features, such as roof eaves, fascias, beam, doors, doorjambs, siding, and trim, need caulking and painting to preserve and to prevent moisture inundation.								
DECKS	Decks:	\square Generally satisfactory where visible $\ \square$ See summary $\ oxdot$ N/A							
BALCONIES STOOPS	Balconies:	\square Generally satisfactory where visible $\ oxtimes$ See summary $\ oxtimes$ N/A							
STEPS	Stoops:	\square Generally satisfactory where visible $\ \square$ See summary $\ oxdot$ N/A							
AREAWAYS	Steps:	☐ Generally satisfactory where visible ☒ See summary ☐ N/A							
PORCHES RAILINGS	Areaways:	\square Generally satisfactory where visible $\ \square$ See summary $\ oxdot$ N/A							
KAILINGS	Porches:	☐ Generally satisfactory where visible ☐ See summary ☒ N/A							
	Railings:	☑ Generally satisfactory where visible ☐ See summary ☐ N/A							
	Comments: (1) Th replaced as neede	e exterior entry steps have edge damage where the bricks need to be monitored and ed.							

SITE CONDITIONS

SITE – WITH	Retaining walls:	☐ Generally satisfactory where visible ☐ See summary ☒ N/A
RESPECT TO THEIR	Yard fencing:	☐ Generally satisfactory where visible ☒ See summary ☐ N/A
EFFECT ON	Vegetation:	$oxtimes$ Generally satisfactory where visible \Box See summary \Box N/A
THE	Grading:	\square Generally satisfactory where visible $\ oxtimes$ See summary $\ oxtimes$ N/A
CONDITION OF THE	Drainage:	\square Generally satisfactory where visible $\ oxtimes$ See summary $\ oxtimes$ N/A
BUILDING	Walkways:	$oxtimes$ Generally satisfactory where visible \Box See summary \Box N/A
	Patios:	$oxtimes$ Generally satisfactory where visible \Box See summary \Box N/A
	Drive:	$oxtimes$ Generally satisfactory where visible \Box See summary \Box N/A
	Gates:	☐ Generally satisfactory where visible ☒ See summary ☐ N/A
	Typical automotive flat and should be reponding along the pool barrier protect the house walls. The ground valve box a dirt/ debris below to low masonry walls masonry fence wall corner. The wall ap	e limbs and vegetation should be kept trimmed back from roof and wall surfaces. (2) stains are visible at garage and driveway concrete. (3) Yard areas appear generally monitored and re-graded as needed to slope down and away from the home to avoid exterior stem wall. (4) The east yard gate was locked and not able to be tested for tion. (5) Sprinklers need to be adjusted or relocated as needed to not overspray onto here appears to be a leak in the landscape system where water is pooling near the at the east yard area. There appears to be a ground watering valve box filled with the gutter termination east of the garage that needs further evaluation. (6) The yard and pilasters have some separation at mortar joints and need repair. (7) The west I has large movement cracks at several areas including the pilaster at the southwest opears stable but needs to be monitored.
	ety glazing, shutters, seas served by inspectors.	sonal accessories, outbuildings, recreational facilities, fences, soil and geological conditions are not
•	· ·	h. around, and between door and window frames and glass, including broken seals or condensation

Note: Moisture and air infiltration through, around, and between door and window frames and glass, including broken seals or condensation between the glass, is not part of this inspection and should be investigated by others. These conditions can occur over time and without being visible during initial inspection and would be considered a latent defect.

Note: Building improvement setbacks to property lines or easements are not part of this inspection.

SYSTEM: ROOFING

ROOF	$oxtimes$ Roof readily accessible \Box Inspected off ladder at eaves and from ground								
COVERINGS	☐ Not accesse	ed from roof due to potential for damage to the tiles							
	Signs of past or present roof leaks: ⊠ Visible ⊠ See summary								
	Water ponding: ⊠ Typical ponding ☐ Excessive ponding ☐ See summary								
	Type: Built- uբ	p: ☐ Felt/bituminous ☐ Gravel/rock ☐ Urethane							
	Condition:	☐ Appears satisfactory where visible ☐ See summary							
	Type: Shingle:	☐ Composition ☒ Wood ☒ Shake ☐ Other							
	Condition:	☑ Appears satisfactory where visible ☑ See summary							
	Type: Tile:	☐ Clay tile ☐ Cement tile ☐ Other							
	Condition:	☐ Appears satisfactory where visible ☐ See summary							
	Comments: (1) Vegetation and debris should be removed from the roof surfaces.							
FLASHINGS	Roof flashings	: \square Satisfactory where visible \boxtimes See summary							
	Roof to wall fl	ashings: ☐ Satisfactory where visible ☒ See summary							
	Comments:								
SKYLIGHTS CHIMNEYS	Sky light condition:	\square Adverse conditions \square No visible adverse conditions							
VENTS		☐ See summary ☒ N/A							
JACKS	Chimney	\square Adverse conditions \boxtimes No visible adverse conditions							
	condition:	\square See summary \square N/A \square Spark arrester installed							
	Vent/Jack	oxtimes Adverse conditions $oxtimes$ No visible adverse conditions							
	condition:								
	Comments: (1) Roof vents, jacks, and penetrations will need periodic mesh and recoating.							
ROOF	Scuppers:	☐ Satisfactory where visible ☐ Need cleaning ☒ N/A							
DRAINAGE SYSTEMS	Gutters:	\square Satisfactory where visible $\ \boxtimes$ Need cleaning $\ \square$ N/A							
	Roof Drains:	\square Satisfactory where visible \square Need cleaning \boxtimes N/A							
	Down-spouts:	\square Satisfactory where visible $\ oxtimes$ Need cleaning $\ \Box$ N/A							
	Splash blocks:	\square Satisfactory where visible \square Need cleaning \boxtimes N/A							
) Note: It is unknown if gutters leak or are properly sloped to drain.							
		or membranes below roof tiles, shingles, or wood shakes is unknown and cannot be inspected without Inspectors do not access roof if roof is too high or too steep or could be damaged by accessing it.							

Note: The condition of roof felt paper or membranes below roof tiles, shingles, or wood shakes is unknown and cannot be inspected without possible damage to the roof coverings. Inspectors do not access roof if roof is too high or too steep or could be damaged by accessing it. Antennas, solar systems, and other attachments are not inspected in this report. No guarantee or warranty is made by this inspection whether the roof leaks at the time of inspection or is subject to future leaking.

SYSTEM: PLUMBING

EXTERIOR	Main shut-off location: sou	ıth exterior	r									
SUPPLY LINES	Lines where visible: ⊠ Copper ☐ Galvanized ☐ CPVC ☐ PVC ☐ Other											
	\square Insulated \boxtimes Not insulated \square not visible \boxtimes Not fully visible											
	Condition: Appears satisfactory where visible See summary											
	Functional flow: General	ally functio	nal 🗆 S	See sun	nmary							
	Anti-siphon devices: ⊠ Ho	se bibs 🗵	None [⊠ See s	umma	ary						
	Sewer line cleanout(s): ⊠	Visible 🗆	Not visi	ble								
	Sewer line cleanout location Comments: (1) The pressur corrosion and past leakage repaired as needed. (2) The bibs. (3) Due to the age of the plumber.	re type vac at the eas e installatio	uum brot t and scoon of an	outh ex iti-sipho	teriors on dev	and sh	nould l neede	be mo d at al	nitor Il exte	ed and erior h	l ose	
INTERIOR	Visible water lines: ⊠ Cop	per 🗆 Gal	vanized	□СР	/C 🗆	Polybu	tylene	!				
SUPPLY LINES	☐ Supported ☐ Imprope	rly support	ted ⊠ l	Jndete	rmine	d⊠No	ot fully	/ visibl	e			
	☐ Insulated ☐ Not insula	ated 🗵 Un	determi	ined ⊠	l Not f	ully vis	ible					
	☑ Appears satisfactory w	here visible	e 🗆 See	e summ	ary							
	Visible drain, waste and ve	nt lines: 🗵	ABS [☐ Cast i	ron 🗆	Galva	nized	steel				
	☐ Supported ☐ Imprope	erly support	ted ⊠ l	Jndete	rmine	d⊠No	ot fully	/ visibl	e			
	☑ Appears satisfactory w	here visible	e □ See	e summ	ary							
	Attic water lines: ☑ N/A ☐ Copper ☐ Galvanized ☐ CPVC ☐ Polybutylene											
	☐ Supported ☐ Imprope	rly support	ted □ l	Jndete	rmine	d⊠No	ot fully	visibl	e			
	☐ Insulated ☐ Not insula	ated 🗆 Un	determi	ined 🗵	l Not f	ully vis	ible					
	☐ Appears satisfactory w	here visible	e □ See	e summ	ary							
	Cross connections: ☐ Obs	erved ⊠ N	lone ob	served	□ Se	e sumn	nary					
	Comments:											
MISCELLANEOUS WATER FIXTURES	Kitchen:	□ Function	nal 🗆 N	lonfunc	tional	□ See	sumn	nary				
AND FAUCETS	Laundry:		nal 🗆 N	lonfunc	tional	⊠ See	sumr	nary				
	Wet bar:	☐ Function	nal 🗆 N	lonfunc	tional	⊠ N/A	Ą					
	Whirlpool:	☑ Function	nal 🗆 N	lonfunc	tional	□ N/A	A					
	Sump pumps:	☐ Function	nal 🗆 N	lonfunc	tional	⊠ N/A	4					
	Sewage ejector pumps:	☑ Function	nal 🗆 N	lonfunc	tional	□ N/A	A					
D.I	Comments:	2.5				1						
Bathroom Locations:	1. Hall Bath, 2. Master Bath							, 6.		, 7.		, 8.
		_ 1	2	3	4	5	6	7	8			

COUNTERTOPS	Functional/ normal wear:	\boxtimes	X	N/A	\boxtimes					
SURROUNDS AND CABINETS	See summary:									
AND CADINETS	Comments:									
TOILETS		1	2	3	4	5	6	7	8	
	Functional/ normal wear:	\boxtimes	\boxtimes		\boxtimes					
	See summary:	\boxtimes		\boxtimes						
	Comments:									
FAUCETS		1	2	3	4	5	6	7	8	
SHOWERHEADS	Functional/ normal wear:	\boxtimes	\boxtimes	\boxtimes	\boxtimes					
	See summary:				\boxtimes					
	Comments:									
BATHROOM		1	2	3	4	5	6	7	8	
EXHAUST FANS	Generally functional:	\boxtimes	\boxtimes	\boxtimes	\boxtimes					
	See summary:									
	Window ventilation:									
	Comments:									
LAUNDRY ROOM	Generally functional:	\boxtimes								
EXHAUST FAN	See summary:									
	Window ventilation:									
	Comments:									
FUNCTIONAL		1	2	3	4	5	6	7	8	
DRAINAGE:	Functional/ normal wear:	\boxtimes	\boxtimes	\boxtimes	\boxtimes					
SINKS TUBS	See summary:									
SHOWERS	Comments:									
Note: Water stop valves a	and overflows are not checked. Fixtu	res and t	rim are	checked	for fund	tion onl	y and no	ot for co	smetic v	alue.

WATER HEATER

WATER HEATER	Location: garage						
MAKE: Rheem	Type: ☐ Gas ☒ Electric ☐ Solar Capacity: 50 gallon						
MODEL:	Condition: $oxtimes$ Appears generally operational $oxtimes$ Appears inoperative						
XE50T06ST45UO SERIAL #:	Normal operating controls: ☑ Appear satisfactory where visible ☑ See summary						
RH M341413445	Automatic safety controls: ⊠ Observed ⊠ Not operated						
	Temperature/Pressure relief valve and line: See summary						
	Signs of leakage: ☑ None ☐ See summary						
	Chimneys, flues, and vents (gas): ⊠ N/A □ Appears satisfactory where visible						
	Combustion air vents (gas): ☑ N/A ☐ Appears satisfactory where visible						
	Comments: We recommend the installation of an overflow pan at the interior water heater. (2)						
	The water heater top shut-off valve is slightly corroded and needs to be monitored and replaced as						
	needed. (3) Although beyond the scope of this inspection: the soft water unit shows signs of past						
	leakage and needs to be further evaluated and corrected as needed. This device was not						
	operational at the time of inspection. (4) The water heater relief line does not extend to the						
	exterior and needs correction.						
Note: Inspectors are no	t required to determine source of water supply, operate any valve except water closet flush valves, fixture faucets, and hose bibs.						

Note: Solar systems, septic systems, wells, filters, conditioners, yard landscape watering systems, and fire sprinklers are not a part of this inspection.

SYSTEM: ELECTRICAL

SERVICE	Service entrance type: ☐ Overhead ☐ Underground									
ENTRANCE	Condition: ☑ Appears satisfactory where visible ☐ See summary									
	Service entry conductor type: ☐ Copper ☐ Aluminum ☒ Not visible									
	Voltage: <u>120/240</u> Amperage: <u>200</u> □ See summary									
MAIN	Main overcurrent device: $oxtimes$ Breaker $oxtimes$ Fuse $oxtimes$ Lever $oxtimes$ Undetermined									
DISCONNECT	Condition: $oxtimes$ Appears satisfactory where visible $oxtimes$ See summary									
	Comments:									
SERVICE	Location(s): south exterior									
PANEL	Branch circuit overcurrent devices: $oxtimes$ Breakers $oxtimes$ Fuses $oxtimes$ Undetermined									
	Branch wiring: $oxtimes$ Copper $oxtimes$ Aluminum $oxtimes$ Not visible $oxtimes$ Undetermined $oxtimes$ Not fully visible									
	Condition: $oxtimes$ Appears satisfactory where visible $oxtimes$ See summary									
	Compatibility of over-current devices to their ampacities and voltages:									
	$oxtimes$ Appears satisfactory where visible \Box See summary									
	Wiring to heavy appliances: $oxtimes$ Copper $oxtimes$ Aluminum $oxtimes$ Not fully visible $oxtimes$ Not visible									
	Ground wire: ☐ Copper ☐ Aluminum ☒ Undetermined									
	Panel labeled: ☐ Yes ☒ Somewhat ☐ No									
	Condition of panel: \square Appears satisfactory where visible \boxtimes See summary									
	Comments: (1) There is a 30-amp breaker inside the main panel set in the off position. This breaker label									
	is not legible but appears to be for the basement HVAC system as that system is not functional. This needs further evaluation.									
EXTERIOR	Receptacles: ☐ GFCI ☒ Not GFCI ☒ See summary									
WIRING	Representative number of lighting fixtures, switches and receptacles:									
	☑ Generally functional ☑ Nonfunctional ☑ See summary									
	oxtimes Correct polarity $oxtimes$ Grounded $oxtimes$ Open ground									
	Comments:									

	•						
INTERIOR	Bathroom receptacles:	☐ GFCI ☐ Not GFCI ☐ See summary					
WIRING	Kitchen receptacles:	☑ GFCI □ Not GFCI ☑ See summary					
	Laundry receptacles:	☐ GFCI ☒ Not GFCI ☒ See summary ☐ N/A					
	Wet bar receptacles:	☐ GFCI ☐ Not GFCI ☐ See summary ☒ N/A					
	Garage receptacles:	☐ GFCI ☒ Not GFCI ☒ See summary ☐ N/A					
	Representative number of	f lighting fixtures, switches and receptacles:					
	☐ Generally functional ☐ Nonfunctional ☐ See summary						
	⊠ Correct polarity □ Inc.	correct polarity ⊠ Grounded □ Open ground					
	Comments: (1) Exterior and interior light fixtures do not function or do not completely function a						
	random areas throughout. Bulbs? Further evaluation and repair or replacement is needed.						
Note: A representative number of switches and receptacles that are readily accessible are tested. Inspectors are required to observe but not							
determine adequacy of electrical panels and current capacity – not within the scope of this report.							
Note: Low voltage systems, stereos, intercoms, vacuum systems, security systems or other low voltage systems are not inspected.							

SYSTEM: HEATING

UNIT #1	Location and type: split system heat pump						
	Energy source: ⊠ Electric □ Gas □ Solid fuel						
	Unit: ☐ Operational ☒ See "Note" at bottom of page						
	Comments:						
UNIT #2	Location and type: electrical heater						
	Energy source: ⊠ Electric □ Gas □ Solid fuel						
	Unit: ☐ Operational ☒ See summary						
	Comments: The unit was not functional and did not respond to the thermostat.						
UNIT #3	Location and type: split system heat pump						
	Energy source: ⊠ Electric □ Gas □ Solid fuel						
	Unit: ☐ Operational ☑ See "Note" at bottom of page						
CONTROLS/	Comments:						
CONTROLS/ VENTS	Normal operating control (Thermostat): ⊠ Appears functional ⊠ See summary						
VEIVIS	Chimneys, flues and venting: ☐ Generally functional ☐ See summary ☒ N/A						
DISTRIBUTION	Comments:						
DISTRIBUTION SYSTEM	Heat distribution systems - fans, pumps, ducts and piping, with supports, blower, dampers, insulation, registers, radiators, fan coil units, convectors:						
SISILIVI	☐ Observed ☐ Generally operable ☐ See summary						
	Supply ductwork: ⊠ Wire flex ⊠ Rigid □ Underground ⊠ Not fully visible						
	···						
	☐ Insulated ☐ Not insulated ☐ Undetermined						
	Return ductwork: ☐ Wire flex ☒ Rigid ☒ Underground ☒ Not fully visible						
	☐ Supported ☐ Not supported ☒ Undetermined						
	☐ Insulated ☐ Not insulated ☒ Undetermined						
	Returns: ⊠ Appears satisfactory where visible ☐ See summary						
	Air filters location(s): at air handlers						
	☐ Appears satisfactory where visible ☒ See summary						
	Comments: (1) We recommend monthly replacement of the air filter(s).						
SAFETY CONTROLS	Gas lines: ☐ Appears satisfactory where visible ☐ See summary ☒ N/A						
CONTROLS	Gas shut-offs: ☐ Appears satisfactory where visible ☐ See summary ☒ N/A						
	Comments:						
AIR SUPPLY	☑ Supplied to all major living areas ☐ See summary						
	There is presence of installed heating source in each of the following rooms:						
	Bedrooms, bathrooms, loft, dining room, living room, family room, kitchen, basement						
	□ Adverse conditions □ No visible adverse conditions □ See summary						
	Comments:						

Note: Inspectors are not required to observe humidifiers, electronic filters, interior of flues, adequacy or uniformity of air supply to various rooms, or operate systems that have been shut down or when weather conditions may cause damage to the equipment. **Note:** This inspection does not include heat exchangers, which may or may not have cracks or holes. If this is of concern, a licensed heating contractor should investigate.

Note: Unit not checked for heating function due to time of year and potential for damage if switched from cooling to heat then back again.

SYSTEM: CENTRAL AIR CONDITIONING

UNIT #1 MAKE:	Location and type: split system heat pump: west exterior south ground unit with pantry closet air handler							
Trane 06/2003	Temperature spread: Appears satisfactory □ See summary							
MODEL: 354523B2F	Unit condition: ☑ Appears functional ☐ See summary							
SERIAL #:	Energy source: Electric [•					
2A6H40481000AA	Landing and town onlike out							
UNIT #2 MAKE:	handler	em a/c: west exterio	r middle ground unit with basement ceiling air					
TRANE 10/86	Unit condition: ☐ Appears f	functional ⊠ See su	mmary					
MODEL: BTD724A100C1	Energy source: ⊠ Electric □	☐ Gas						
SERIAL #: S42223959	Comments:							
UNIT #3 MAKE:	Location and type: split system handler	em heat pump: west	t exterior north ground unit with hall closet air					
TRANE 07/2008	Temperature spread: 🛛 App	pears satisfactory □	l See summary					
MODEL: 4TWR4030A1000AA	Unit condition: ☑ Appears f	functional ☐ See su	mmary					
SERIAL #: 8313YS72F	Energy source: ⊠ Electric [□ Gas						
CONTROLS								
CONTROLS	Normal operating control (1) Comments:	hermostat): 🗵 Appe	ears functional ⊠ See summary					
DISTRIBUTION	A/C distribution systems - fa		d piping, with supports, dampers, insulation,					
SYSTEM	registers, radiators, fan coil u	·						
	☑ Observed ☑ Generally	·	·					
	Supply ductwork: Wire floor	_	·					
		Not supported	☑ Undetermined					
		Not insulated	□ Undetermined					
	Return ductwork: Wire fl	_						
		Not supported	☑ Undetermined					
		Not insulated	□ Undetermined					
	Returns: Appears satisfaction Air filters location(s): at air h	•	☐ See summary					
	☐ Appears satisfactory wh		ımmarv					
			•					
	Comments: (1) We recomme	•	•					
AIR SUPPLY	☑ Supplied to all major living	g areas	mary					
	There is presence of installed	•	•					
			ditions See summary					
	☐ Adverse conditions ☐ No visible adverse conditions ☐ See summary							

Comments:

Note: We recommend the heating and cooling system be cleaned and serviced seasonally.

Note: It should be expected that due to the age of the heating and air conditioning unit(s), that components might fail at any time.

SYSTEM: INTERIORS

☐ Generally satisfactory where visible ☐ Normal wear ☐ See summary					
Fire separation walls: \square attic fire walls \square multiple dwelling fire walls					
☐ generally satisfactory where visible ☐ See summary ☒ n/a					
Comments: (1) Due to the age of this home defects may be present at concealed areas such as below grade, under attic insulation, in wall and ceiling cavities, and under flooring. (2) Due to the recent remodel defects may be present and concealed.					
☐ Generally satisfactory where visible ☐ Normal wear ☐ See summary					
Fire separation ceilings: ☑ Garage fire separation ceiling					
$oxtimes$ Generally satisfactory where visible \Box See summary \Box N/A					
Comments:					
☑ Carpet ☑ Tile ☑ Wood ☐ Vinyl ☐ Laminate ☐ Other					
☑ Generally satisfactory where visible ☑ Normal wear ☐ See summary					
Comments: (1) Condition of floor under floor coverings and appliances is unknown. (2) Tile floors should be caulked periodically to tubs, toilets, cabinets, baseboards, etc., for moisture protection.					
A representative number of doors and windows:					
☐ ☑ Generally operable ☐ Generally satisfactory where visible ☐ See summary					
Fire separation door between garage and house: ☑ Generally satisfactory where visible ☐ See summary ☐ N/A					
Steps/ Stairs: ☐ Generally satisfactory where visible ☒ Normal wear ☒ See summary					
Balconies/ Rails: ☐ Generally satisfactory where visible ☒ Normal wear ☒ See summary					
Comments:					
☐ Functional ☐ None observed ☒ See summary					
Comments:					
Note: Smoke detector testing is limited to pressing the test button for audible response. Hard wire or					
battery backup is not tested. Note: It is recommended that smoke detectors over ten years old be replaced.					
Note: We recommend the installation of carbon monoxide detectors due to gas fixtures.					

FIREPLACES

FIREPLACE #1	Location(s): family room					
	Type: ☑ Masonry ☐ Zero clearance ☐ Natural Gas ☐ Propane ☒ Wood					
	Flue type: ☐ Clay ☐ Metal ☒ Masonry ☐ Direct vent ☐ See summary					
	Dampers: ⊠ Functional □ Nonfunctional □ Removed □ Fixed open □ N/A					
	☐ Generally satisfactory where visible ☐ See summary					
	Comments:					
FIREPLACE #2	Location(s): master bedroom					
	Type: ☑ Masonry ☐ Zero clearance ☐ Natural Gas ☐ Propane ☒ Wood					
	Flue type: ☐ Clay ☐ Metal ☒ Masonry ☐ Direct vent ☐ See summary					
	Dampers: ⊠ Functional □ Nonfunctional □ Removed □ Fixed open □ N/A					
	☑ Generally satisfactory where visible ☐ See summary					
	Comments:					
NOTE: We recommen	nd periodic cleaning of the flue pipe due to creosote build-up.					

SYSTEM: INSULATION AND VENTILATION

ATTIC	Attic access location(s): garage and pantry						
	\square readily accessible/ fully accessed \boxtimes Viewed from scuttle hole off ladder \square N/A						
	☑ The attic was not accessed beyond the scuttle hole or storage platform						
	☑ Vaulted areas were not accessed because there is no access or limited space						
	Comments:						
VENTILATION	Attic ventilat	ion:					
	Туре:	\square N/A \square Turbine \boxtimes Roof \square Gable \square Ridge \square Vented "bird board"					
	Location:	oxtimes Roof $oxtimes$ Under eave $oxtimes$ Gable wall $oxtimes$ Other					
	Condition:	\square Satisfactory where visible \boxtimes Poor \square None \boxtimes See summary					
	Crawlspace v	rentilation:					
	Type:	☑ N/A □ Open □ Mechanical □ Open □ None					
	Location:	☐ Foundation walls ☐ Through floor ☐ Other					
	Condition:	\square Satisfactory where visible \square Poor \square See summary					
	Dryer ventila	tion:					
	Location:	☑ Through roof □ Through wall □ N/A					
	Condition:	$oxtimes$ Appears satisfactory where visible \Box See summary					
	Visible ducts/vents: ⊠ Appears satisfactory where visible ☐ See summary						
	Comments:						
INSULATION	Wall insulation type: ⊠ Undetermined ⊠ Not visible- not inspected						
	Attic insulation type: ⊠ Batt □ Blown □ Cellulose ⊠ Fiberglass □ Rock wool						
	Attic insulation depth: 6" to 9" (+/-) \boxtimes Not fully visible \square See summary Attic insulation condition:						
	☐ Appears	satisfactory where visible ☑ Displaced ☐ Damaged ☒ Missing					
	Vaulted ceilir	ngs: □ N/A □ Visible 図 Not visible					
	Vapor retarders: ☐ Building paper ☐ Plastic ☐ Other ☒ None visible (typical)						
	Comments:						

KITCHEN AND BUILT-IN APPLIANCES

CABINETS AT	A representative number of cabinets:
RANDOM	Condition: ☑ Satisfactory where visible ☑ Normal wear ☐ See summary
	Comments:
COUNTERTOPS	Condition: ☑ Satisfactory where visible ☑ Normal wear ☐ See summary
	Comments:
DISHWASHER	Condition: ☐ Appears functional ☐ Normal wear ☒ See summary
	Comments:
DISPOSAL	Condition: ☐ Appears functional ☐ Normal wear ☒ See summary
	Comments:
СООКТОР	Condition: ☐ Appears functional ☐ Normal wear ☒ See summary
	Comments:
OVENS	Condition: ☑ Appears functional ☑ Normal wear ☐ See summary
	Comments:
EXHAUST FAN/	Location: \square At microwave \square At hood \boxtimes At stovetop \square None
STOVE VENT	Ventilation type: \square Vented \square Self-vented \boxtimes Downdraft vent \square Other
	Condition: ☐ Appears functional ☒ See summary
	Comments:
MICROWAVE	Condition: ☑ Appears functional ☑ Normal wear ☐ See summary
	Comments:

POOL, SPA & EQUIPMENT

GENERAL	Type:	Above grour	nd pool Below ground pool		
CONDITION	×	Pool/Spa co	mbination Separate pool and spa		
	Finish:	Plaster □ Pe	ebble-surface Fiberglass Vinyl liner		
	Condition:	Normal wea	r ⊠ Wear/damage		
	X	Generally cl	ean ⊠ Not clean □ Algae present		
	Aerator:	Generally sa	tisfactory ⊠ See summary □ N/A		
	Aerator valve:	☐ Generally satisfactory 区 See summary ☐ N/A			
	Auto Filler:	☐ Generally satisfactory ☐ See summary ☐ Anti-siphon valve ☒ N/A			
	Comments: (1) The pool equipment and valves need to be labeled for easy operation and prevention of damage. (2) The pool equipment water lines need to be painted for ultraviolet protection. (3) The pool equipment aerator valve handle is seized and needs replacement. (4) The gap between the pool wall and skimmer liner needs to be sealed.				
CLEANING	Type:	In-floor pop	-ups ⊠ Suction head (Vacuum) □ Pressure head □ None		
SYSTEM	X	Operating [☐ Not operating		
	Comments:				
EQUIPMENT		ers, skimmers, drains, gauges, visible piping and valves:			
		ıaı ⊔ Wear/ı	Damage noted ⊠ See summary		
FILTER		omaceous ea	arth □ Cartridge ☒ Backflush not tested		
			Damage noted □ See summary		
	Comments:				
DECK	Deck condition: Step/Seat condition (internal): Step/Ladder condition (external):		$oximes$ Typical for age \oximes Wear/Damage \oximes See summary \oximes N/A		
STEPS/SEATS COPING			☑ Typical for age ☐ Wear/Damage ☒ See summary ☐ N/A		
TILE			☐ Typical for age ☐ Wear/Damage ☐ See summary ☒ N/A		
HANDRAILS	Coping condition: Tile condition: Grout seam condition: Handrail condition: Ladder condition:		☐ Typical for age ☒ Wear/Damage ☒ See summary ☐ N/A		
LADDERS			☐ Typical for age ☒ Wear/Damage ☒ See summary ☐ N/A		
			☑ Typical for age ☐ Wear/Damage ☐ See summary ☐ N/A		
			☑ Typical for age ☐ Wear/Damage ☐ See summary ☐ N/A		
			☐ Typical for age ☐ Wear/Damage ☐ See summary ☒ N/A		
	Comments:				
ELECTRICAL	Underwater lighting:	⊠ Pool □	Spa		
	Condition:	☑ Appears	operational Damage noted See summary		
	GFCI outlet:	⊠ Operation	onal □ Not operational □ See summary □ N/A		
	Conduit:	☑ Appears	functional Wear/Damage See summary N/A		

	Components: ⊠ Typical for age □ Wear/Damage ⊠ See summary □ N/A					
	Timer assemblies: ☑ Typical for age ☐ Wear/Damage ☐ See summary ☐ N/A					
	Comments:					
BOND WIRES	Pump motors	: □ External [□ Normal wear □ Wear/damage 🗵 See summary □ N/A			
	Blowers:	☐ External [□ Normal wear □ Wear/damage □ See summary 図 N/A			
	Heaters:	☐ External [□ Normal wear □ Wear/damage □ See summary 図 N/A			
	Comments:					
GROUNDING	Metal objects	within five feet	of pool: □ Bonded □ Not bonded 図 N/A			
	Comments:					
HEATERS	Type:	□ N/A	☑ Gas ☐ Heat pump ☐ Solar ☐ Electric			
	Condition:		$oxtimes$ Appears operational \Box Wear/Damage noted \Box See summary			
	Automatic safety controls:		☑ Observed ☑ Not operated			
	Condition:		☑ Appear satisfactory where visible ☐ See summary			
	Comments:					
CHILD SAFE	Tunou	☐ Fencing ☐ Se	elf-closing/self-latching gate ⊠ Pneumatic door closers			
BARRIERS	Type:	☐ Door alarms	☐ None visible			
	Condition:	☑ Appear satisf	actory where visible 🗵 See summary			
	Comments:					
ENTRAPMENT	☑ Present ☑	None visible				
PREVENTION	Comments:					
NOTE: Underground leaks, operating efficiency of pool or spa are beyond the scope of this report. Pool heaters, salt systems and chlorinators have not						

been inspected and are not part of this report unless otherwise noted. Pool equipment components will not be disassembled. All valves will be left as

NOTE: The buyer(s) should familiarize themselves with the operation of the pool, spa and equipment before operating to prevent damage.

found. Local ordinances should be checked to ensure that pool safety and pool fencing requirements are in compliance.